

Nighttime Closures

Week of Sept. 30, 2024

		vveek	or Sept. 30, A	2024			
Date	9/30/2024	10/1/2024	10/2/2024	10/3/2024	10/4/2024	10/5/2024	10/6/2024
I-5 Lane Reductions/Closures							
Northbound							
SR-73 to Crown Valley Pkwy	8 p.m 6 a.m.	8 p.m 6 a.m.	8 p.m 6 a.m.	8 p.m 6 a.m.	8 p.m 8 a.m.		
Oso Pkwy to Alicia Pkwy	8 p.m 6 a.m.	8 p.m 6 a.m.	8 p.m 6 a.m.	8 p.m 6 a.m.	8 p.m 8 a.m.		
Southbound							
Crown Valley Pkwy to SR-73	8 p.m 6 a.m.	8 p.m 6 a.m.	8 p.m 6 a.m.	8 p.m 6 a.m.			
Alicia Pkwy to Oso Pkwy	10 p.m 5 a.m.	10 p.m 5 a.m.	10 p.m 5 a.m.	10 p.m 5 a.m.			
Lake Forest Dr to El Toro Rd	10 p.m 6 a.m.	10 p.m 6 a.m.	10 p.m 6 a.m.	10 p.m 6 a.m.			
Nightly Ramp Closures							
Avery Parkway							
NB on-ramp	10 p.m 6 a.m.	10 p.m 6 a.m.	10 p.m 6 a.m.	10 p.m 6 a.m.	10 p.m 8 a.m.		
NB off-ramp	10 p.m 6 a.m.	10 p.m 6 a.m.	10 p.m 6 a.m.	10 p.m 6 a.m.	10 p.m 8 a.m.		
SB off-ramp	10 p.m 6 a.m.						
SB on-ramp	10 p.m 6 a.m.	10 p.m 6 a.m.	10 p.m 6 a.m.	10 p.m 6 a.m.	10 p.m 8 a.m.		
Crown Valley Parkway							
NB loop on-ramp	10 p.m 6 a.m.	10 p.m 6 a.m.	10 p.m 6 a.m.	10 p.m 6 a.m.	10 p.m 8 a.m.		
SB off-ramp	10 p.m 6 a.m.	10 p.m 6 a.m.	10 p.m 6 a.m.	10 p.m 6 a.m.	10 p.m 8 a.m.		
Oso Parkway							
NB off-ramp		12 a.m 4 a.m.					
NB loop on-ramp	10 p.m 5 a.m.						
NB on-ramp	10 p.m 5 a.m.						
SB loop on-ramp	10 p.m 6 a.m.		10 p.m 6 a.m.				
La Paz Road							
NB on-ramp			10 p.m 5 a.m.				
SB loop on-ramp		10 p.m 6 a.m.					
SB on-ramp				10 p.m 5 a.m.			
Lake Forest Drive							
NB off-ramp	10 p.m 5 a.m.	10 p.m 5 a.m.	10 p.m 5 a.m.	10 p.m 5 a.m.	10 p.m 7 a.m.		
SB loop on-ramp	10 p.m 5 a.m.	10 p.m 5 a.m.	10 p.m 5 a.m.	10 p.m 5 a.m.			
		Lane Reduction	ns/Closures on L	ocal Streets			
Lake Forest Drive							
Eastbound	10 p.m 5 a.m.	10 p.m 5 a.m.	10 p.m 5 a.m.	10 p.m 5 a.m.	10 p.m 7 a.m.		
La Paz Rd							
Eastbound					11 p.m 5 a.m.		
El Toro Road							
Eastbound		9 p.m 5 a.m.	9 p.m 5 a.m.	9 p.m 5 a.m.	9 p.m 5 a.m.		
Westbound		9 p.m 5 a.m.	9 p.m 5 a.m.	9 p.m 5 a.m.	9 p.m 5 a.m.		
The sch	edule is subject to	change due to	inclement wea	ather or unfores	seen operations	al issues.	

STAY INFORMED



















